



5/10/2023

**ADDENDUM, A**

1. A question was asked regarding cleaning using hand tools, and compressed air for the surface cracks.

We would point you to Iowa DOT Spec: 2307.03 B. 1. The spec is silent on the use of compressed air. We would expect the use of compressed air to be necessary if required to clean the cracks. The road being seal coated is a new overlay in 2019 and had router and crack sealing performed in 2022.

2. An area for bid unit prices was also added to the RFP.

Plans and RFP and Addendum's are available on the Osceola County Engineers Website:

<https://osceolacountyia.gov/departments/engineer/>